

US EPA ARCHIVE DOCUMENT

| | | | |
|--|--|--------------------------------|---|
| UNIT LOG | 1. Incident Name Kalamazoo River/Enbridge Oil Spill | 2. Date Prepared 04/13/2012 | 3. Time Prepared 1600 |
| 4. Unit Name/Designators Situation Unit | 5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief | | 6. Operational Period 0700, 04/12/12 – 0700, 04/19/12 |
| 7. Personnel Roster Assigned | | | |
| Name | | ICS Position | Home Base |
| Matthew Haak | | Situation Unit Leader | Houston, Texas |
| 8. Activity Log | | | |
| Time | Major Events | | |
| 11:00 | <p>Overflight Operational status:</p> <ul style="list-style-type: none"> MP0.75, sheen observed LDB Talmadge Creek. MP1.0 LDB, sheen observed along Talmadge Creek. MP1.75 LDB, sheen observed along Talmadge Creek. Sheen observed along Talmadge Creek at A Drive. Buoy Cans deployed at Saylor's landing. Observed Ceresco Dam containment boom. MP9.0R1, sheen observed in side channel. MP15.25 Mill Pond, sheen observed along the LDB. MP15.75 Containment Boom, observed SWAT. MP15.0 LDB, sheen observed on overbank. MP21.5, observed crews. MP21.5 LDB, sheen observed in area where RI crew was working. RI crew observed near MP30.5. MP30.8, new boom deployed. MP35.00 LDB, sheen observed LDB. MP36.5 LDB, sheen observed. Observed poling Crew on Lake Morrow. Sheen observed on Lake Morrow. | | |
| | Additional observations: None | | |
| 15:00 | Return to ICP. | | |
| 9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START | | | |